

TANK PUMPING REPORT

Site Name:

Location: 1156 RIDGEWAY DR
OAK HARBOR
Tax ID: S8390-00-00007-0
Use:

Service Company:

Dirty Deeds Septic Services

1004 Commercial Ave #450
Anacortes, WA 98221
360-622-9092

Serviced: 09/24/2025 by: Keith Jordan

Submitted 10/04/2025 by: Keith Jordan

Dump Location: Anacortes Waste Water Treatment Plant

Jurisdiction ID: S8390-00-00007-0

COMMENTS

Septic tank is not in good condition and has deterioration and root intrusion around inlet and outlet.

Penetration points for the inlet and outlet both are not sealed.

Septic tank lid has radiating cracks throughout the lid that travel from inlet to outlet.

The on-site sewage system will require an inspection and then evaluation by a septic designer. The reported conditions and deficiencies from this pumping report and future inspection report, will assist in determining corrective actions.

TANK: Septic Tank - 1 Compartment

Total Gallons pumped from tank (Number only, no text):	975	
Effluent level within operational limits (if NO explain in comments):	YES	
Effluent returning back into tank after pumping:	NO	
Access Risers installed to grade (N/A if not present):	YES	
Tank Condition Good:	NO	Deficient
Baffles in good condition (N/A if not present):	YES	
Effluent screen cleaned (N/A if not present):	YES	
Effluent surfacing around site components (N/A if not checked):	NO	
Were repairs made to the Tank or Tank Components? (if YES explain in comments):	NO	

This report indicates certain characteristics of the onsite sewage system at the time of visit. In no way is this report a guarantee of operation or future performance.



This report indicates certain characteristics of the onsite sewage system at the time of visit. In no way is this report a guarantee of operation or future performance.





This report indicates certain characteristics of the onsite sewage system at the time of visit. In no way is this report a guarantee of operation or future performance.

The following image has been uploaded by the company submitting the report



This report indicates certain characteristics of the onsite sewage system at the time of visit. In no way is this report a guarantee of operation or future performance.